




SHAFT SHOWN IN
FULL C.C.W. POSITION

	L	F	T	M
	10	3.5	3.2	0.5
✓	15	7	6	1
	17	8	7	1.5
	20	11	10	2
	25	14	12	4
	30	14	12	4



NUT 1 PC



WASHER 1 PC t=0.4

